


Node Inspection - 3/07/2019 - SMH.08532432

Date of inspection 3/07/2019	Node name SMH.08532432	Node type Sewer Maintenance Hole	Town Brisbane	Location/Street 34 Serenity DR	No. 3.00
Name of operator Hugh	Precipitation No precipitation	Pre-cleaned Yes		Depth to Invert [m] 3.53	Job Number 1

Node material Concrete segments	Shape of Access Circular	Width of access 1050.00			
---	------------------------------------	-----------------------------------	--	--	--

General comment: **Sewer**



Observations

Nr.	Depth [m]	Code	Observation	Remarks
1	0.02	HSTAC	Start feature, access cover.	
2	0.47	HSLLCM	Ladder support missing (Ladder clip missing).	
3	2.94	HCNDC	A conduit or ventilation pipe has been connected to the maintenance structure, drop chamber.	
4	3.19	HSLLCM	Ladder support missing (Ladder clip missing).	
6	3.49	HCPCI	A conduit connecting to the maintenance structure, circular, incoming. at 1 o'clock	
5	3.52	HCPCO	A conduit connecting to the maintenance structure, circular, outgoing. at 9 o'clock	

Entries (In-Outlets)

No.	Direction	Drop [m]	Clock Position	Shape	Material	Diameter 1 [mm]	Diameter 2 [mm]	Remarks
1	In	3.49	6	Circular		150		
2	Out	3.52	12	Circular		150		

Node Pictures - 3/07/2019 - SMH.08532432

Date of inspection	Node name	Town	Location/Street	Name of operator
3/07/2019	SMH.08532432	Brisbane	34 Serenity DR	Hugh



1, , 0.47
 Ladder support missing (Ladder clip missing).



2, , 0.47
 Ladder support missing (Ladder clip missing).

WinCan VX SAMPLE



3, , 3.19
 Ladder support missing (Ladder clip missing).



4, , 3.49
 A conduit connecting to the maintenance structure, circular, incoming. at 1 o'clock

Clever Scan - 3/07/2019 - SMH.08532432

No.	Node name	Alternative ID	Client's Job Ref	Contractor's Job Ref
3	SMH.08532432			

